



# TagID

## Firmware Update 1.2.2.0

### New Features

- Gateway can set the time on the TagID directly (without the charger)
- The temperature sensor error remains active until the error is reset in the service menu on the charger (red LED flashes continuously)
- Speed of data readout of TagID events was improved

### Bug fixes

- Various Bug fixes

# TagID

# Firmware

# Update 1.2.0

## New Features

- Battery Warm Up Mode:  
Tag ID provides the calculated temperature ranges for the charger

## Changes

- Deep Discharge Detection: Threshold was increased
- SOC Calculation was adjusted

# TagID

# Firmware

# Update 1.1.0

## New Features

- Communication with Gateway

## Changes

- Level sensor position error Switching threshold changed from > 60V to switching threshold with hysteresis:
  - > 30V error is set
  - < 20V error is reset

## Bug fixes

- Various Bug fixes

# TagID

## Firmware Update 1.0.1

### Improvements

- If a new battery configuration is imported, which is not marked as „new“, the SOC is still measured at the battery.
- This makes the following functions available:
  - Battery metrics for SOC are recorded
  - If a low level is detected, the blue LED lights up not only after a completed charge, but also after a certain SOC throughput has been reached
  - Triggering of electrolyte circulation is started